



www.9AutoMotion.com

9 Auto Motion Independent Porsche Specialists

1821 West 10th Street
Riviera Beach, FL 33404
(561) 990-2911
office@9automotion.com
www.9AutoMotion.com
FL Reg: L18000185577
Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
Payment Term: On Receipt
Service Writer: Barbie Valdes

2010 Porsche 911 GT3
VIN: WP0AC2A98AS783322

Recommendations

- Requires New Starter

Annual Oil Service and Vehicle Inspection

Description	Price	QTY	HRS	Disc	Subtotal
Labor: Engine Oil Service			2		\$350.00
Part: Engine Oil Filter		1			\$0.00
Part: Mobil1 0W-40 Advanced Full Synthetic Engine Oil	\$15.95	8		\$27.60	\$100.00
Discount (5.78%): \$27.60 Shop Supplies: \$34.95					Subtotal: \$484.95

Replace Starter Motor

Description	Price	QTY	HRS	Subtotal
Labor: Replace Starter			2	\$450.00
Part: Starter Motor, Rebuilt	\$387.39	1		\$387.39
				Subtotal: \$837.39

Lug Maintenance, Regrease Lugs with Correct Grease

Description	HRS	Subtotal
Labor: Lug Maintenance, Regrease Lugs with Correct Grease	0.5	\$112.50
		Subtotal: \$112.50



www.9AutoMotion.com

9 Auto Motion Independent Porsche Specialists

1821 West 10th Street

Riviera Beach, FL 33404

(561) 990-2911

office@9automotion.com

www.9AutoMotion.com

FL Reg: L18000185577

Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026

Payment Term: On Receipt

Service Writer: Barbie Valdes

Estimate is good for 15 days. This is an approximation of labor and parts/services required to carry out the services requested and/or recommended. It is possible for some deviation from the original estimate to occur once work commences. If any additional repairs and/or parts are required that exceed \$150 above the approved estimate, we will update you with a revised work order providing the cost of any additional parts and labor.

All parts are new unless otherwise specified. We are not responsible for delays caused by unavailability of parts or delay in the delivery of parts. There is no warranty for used parts or customer supplied parts.

Payment Options -

* Visa / Mastercard / AmEx / ApplePay (In-Office 2% Fee) (Payment Link 4% Fee)

* Check / Cash (No Fee)

* Zelle to office@9automotion.com (No Fee)

We will keep you informed and perform only repairs authorized by you.

I hereby authorize the above repairs, including sublet work, along with the necessary materials.

9 Auto Motion LLC and your employees may operate my vehicle for the purpose of on-road testing or inspection. I agree that 9 Auto Motion LLC is not responsible for loss or damage to my vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control. If I cancel repairs prior to completion for any reason, a tear-down and reassembly fee at the going labor rate will be applied. A daily storage charge of \$50/day will be applied two working days after I am notified repairs are completed.

Labor	\$912.50
Parts	\$514.99

Subtotal	\$1,427.49
Discount	\$27.60
Shop Supplies	\$34.95
EPA	\$0.00
Tax	\$0.00

Grand Total	\$1,434.84
Paid to Date	(\$0.00)

REMAINING BALANCE	\$1,434.84
--------------------------	-------------------

Signature _____

Appointments

010 Porsche 911 / Vehicle Vehicle Inspection and Annual Oil Service 997 (2010)

Mon 10/26/26 9:30 AM — 5:30 PM

Messages

Lauren Wardle

10/26/2026 9:02 AM EDT

Hello

We confirm your appointment has been scheduled on October 26, 2026, dropping off at 9:30 AM for your Porsche 911 . Please let us know if you have any questions in the meantime, or if you need to rearrange.

Thank you,

9 Auto Motion Independent Porsche Specialists
1821 West 10th Street, Riviera Beach, FL 33404

Note Shop Hours:

Monday to Friday 9am to 5.30pm, unless otherwise agreed.



9 Auto Motion Independent Porsche Specialists
1821 West 10th Street
Riviera Beach, FL 33404
(561) 990-2911
office@9automotion.com
www.9AutoMotion.com
FL Reg: L18000185577
Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
Payment Term: On Receipt
Service Writer: Barbie Valdes



www.9AutoMotion.com

9 Auto Motion Independent Porsche Specialists
1821 West 10th Street
Riviera Beach, FL 33404
(561) 990-2911
office@9automotion.com
www.9AutoMotion.com
FL Reg: L18000185577
Motor Vehicle Repair Reg: MV100994


Repair Order #92080

Created: 10/23/2026
Payment Term: On Receipt
Service Writer: Barbie Valdes



2010 Porsche 911 GT3
VIN: WP0AC2A98AS783322

Check-In Inspection

Item	Green	Yellow	Red	N/A
1 Additional Customer Notes/Concerns at Drop Off				
Note/Recommendation:				
2 Customer's Schedule / Time Constraints / Preferred Pick-Up Time / Day?				
Note/Recommendation:				
3 Photos / Video of Vehicle - Exterior & Interior				
Note/Recommendation:				
<div></div> <div></div> <div></div>				



9 Auto Motion Independent Porsche Specialists
 1821 West 10th Street
 Riviera Beach, FL 33404
 (561) 990-2911
 office@9automotion.com
 www.9AutoMotion.com
 FL Reg: L18000185577
 Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
 Payment Term: On Receipt
 Service Writer: Barbie Valdes

Item	Green	Yellow	Red	N/A
4 Photos of Mileage & Dashboard				
Note/Recommendation: <div>     </div>				
Totals	0	0	0	4

Porsche Annual Vehicle Inspection / General Inspection

Inspected: 10/26/2026
 Completed: 10/26/2026

Item	Green	Yellow	Red	N/A
1 Road Test	✓			
Note/Recommendation: Check Operation of: <ul style="list-style-type: none"> - Remote Control - Front Seats - Foot Brake & Electric Parking Brake - Engine, Clutch / Transmission - Steering - Park Assist / Cruise Control - PSM, PASM, Sport Switches - Sports Exhaust System - Door Mirror Fold-In Function - Air-Conditioning System - Instruments 				
2 Diagnosis System: Read Fault Memory	✓			



9 Auto Motion Independent Porsche Specialists
 1821 West 10th Street
 Riviera Beach, FL 33404
 (561) 990-2911
 office@9automotion.com
 www.9AutoMotion.com
 FL Reg: L18000185577
 Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
 Payment Term: On Receipt
 Service Writer: Barbie Valdes

Item	Green	Yellow	Red	N/A
Note/Recommendation: Read fault memory, any active or intermittent faults to note? Software updates where applicable.				
3 Windshield Wiper & Washer System	✓			
Note/Recommendation: Windshield Wiper/Washer System Headlight Washer: Check function & nozzle adjustment Check Fluid Levels - Top-up if required				
4 Horn	✓			
Note/Recommendation: Check operation of horns				
5 Tires		✓		
Note/Recommendation: Check Tire Condition Tire Tread Measurements Front Left: *6.1mm / Front Right: *6.1mm Rear Left: *5.0mm / Rear Right: *5.0mm Year/Age of Tires: f 2019 R 2019 F 235/35zr19 pilot sport n2 R 305/30zr19 pilot sport n2				
6 Tire Pressures / TPMS Sensors	✓			
Note/Recommendation: Check Tire Pressures and TPMS Sensors				
7 Battery		✓		
Note/Recommendation: State of charge: (100*%) Cranking Health (Cranking Amps): (*400CA) Passed Advise starter continuing to fail and then work, technician recommends doing a starter if the vehicle is going to be sold.				
8 Electrical Equipment	✓			
Note/Recommendation: Check Operation of Electrical Equipment, including indicator and warning lights				
9 Seat Belts	✓			
Note/Recommendation: Seat Belts: Check function and condition				
10 Locks & Struts	✓			



9 Auto Motion Independent Porsche Specialists
 1821 West 10th Street
 Riviera Beach, FL 33404
 (561) 990-2911
 office@9automotion.com
 www.9AutoMotion.com
 FL Reg: L18000185577
 Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
 Payment Term: On Receipt
 Service Writer: Barbie Valdes

Item	Green	Yellow	Red	N/A
Note/Recommendation: Door Locks: Check function Front Lid Lock: Check lock and safety hook of the front lid function properly Struts: Check front and rear hood shocks function properly				
11 Outside of Vehicle		✓		
Note/Recommendation: Firewall Body Drains: Check for debris Radiators and Air Intakes: Visual check for exterior debris or blockage Underbody panel 997.504.629.92 and passenger side Underbody panel(couldn't find part number on part) damaged from possible track use or off-road event.				
12 Outside of Vehicle	✓			
Note/Recommendation: Check Wiper Blades Vehicle Lighting: Check All Lights Operational Tire Sealant: Check expiration date of tire sealant (where applicable) / replace every 4 years				
13 Brake System	✓			
Note/Recommendation: Brakes: Visual inspection of brake pads and rotors; measurements Brake Hoses & Lines: Visual inspection for damage, correct routing and corrosion Brake Fluid: Check brake fluid level and moisture content * * Note: brake fluid to be changed every 2 years Pads F 8mm R 6mm				
14 Vehicle Underbody	✓			
Note/Recommendation: Underside & Engine: Visual inspection for leaks (oils, fluids) and abrasion (lines, hoses) Underbody Panels: Check for damage and secure installation				
15 Steering Gear & Axle Shafts	✓			
Note/Recommendation: Steering Gear: Visual inspection of dust boots and tie rod ends; check play Axle Shafts: Visual inspection of dust boots and for leaks or signs of wear/damage				
16 Exhaust	✓			
Note/Recommendation: Exhaust: Visual inspection for leaks or damage; check mountings and heat shields				
17 Mounts	✓			
Note/Recommendation: Ancillary Unit Mounts / Chassis and Engine Mounts: Visual inspection of all rubber mountings and boots for wear or damage				
18 Fuel Lines & Connections	✓			



9 Auto Motion Independent Porsche Specialists
1821 West 10th Street
Riviera Beach, FL 33404
(561) 990-2911
office@9automotion.com
www.9AutoMotion.com
FL Reg: L18000185577
Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
Payment Term: On Receipt
Service Writer: Barbie Valdes

Item	Green	Yellow	Red	N/A
Note/Recommendation: <i>Fuel Lines & Connections: Visual inspection for damage or leaks</i>				
19 Coolant Level & Tank Integrity	✓			
Note/Recommendation: <i>Coolant: Check Level and Coolant Tank Integrity</i>				
20 PDCC				✓
Note/Recommendation: <i>PDCC: Check fluid level</i> <i>* Note: Replace PDCC Reservoir every 60k Miles or 6 Years</i>				
21 Drive Belt & Tensioner		✓		
Note/Recommendation: <i>Drive Belt: Check belt(s) for wear; check tensioner is dry</i> <i>* Note: Replace Drive Belt every 40k/60k miles or 4/6 years (model)</i> <i>* Note: Replace Spark Plugs every 30k/40k miles or 3/4 years (model)</i> <i>Drive belt looks original to the car and needs replacement</i>				
Totals	16	4	0	1

Vehicle Check Out

Item	Green	Yellow	Red	N/A
1 Wheels:				
Note/Recommendation: - <i>Wheels Torqued</i> - <i>Tire Pressures Set to Correct PSI</i>				
2 Oil Service:				
Note/Recommendation: - <i>Oil Level Checked</i> - <i>Oil Maintenance Light Reset</i> - <i>Windshield Washer Fluid Level Checked</i>				
3 If Intermediate / Major Maintenance:				
Note/Recommendation: - <i>Maintenance Light Reset</i>				
4 If Repairs Carried Out:				
Note/Recommendation: - <i>CEL Codes Cleared</i> - <i>Coolant Level Checked</i>				



9 Auto Motion Independent Porsche Specialists
1821 West 10th Street
Riviera Beach, FL 33404
(561) 990-2911
office@9automotion.com
www.9AutoMotion.com
FL Reg: L18000185577
Motor Vehicle Repair Reg: MV100994

Repair Order #92080

Created: 10/23/2026
Payment Term: On Receipt
Service Writer: Barbie Valdes

Item		Green	Yellow	Red	N/A
5	Handover:				
Note/Recommendation: - <i>Test Driven & Out Mileage Noted</i> - <i>Wipe Down / Wash, if required</i> - <i>Keys Returned to Front Office</i>					
Totals		0	0	0	5

The inspection performed is a visual and operational assessment of the vehicle's condition at the time of service. Findings are based solely on the observable condition of accessible components and may include notes, photographs, and operation of the vehicle, including road testing, as necessary.

Certain components may be concealed, inaccessible, or require disassembly or additional diagnostic procedures to fully evaluate. It is possible that defects or conditions exist which were not identified during this inspection. Findings reflect the condition of the vehicle at the time of inspection only and do not constitute a warranty or guarantee of future performance or reliability.

This inspection is provided for informational purposes only.

Signature _____