Repasi Motorwerks LLC
1701 Stratford Avenue
Stratford, CT 06615
(203) 257-0987
info@repasimotorwerks.com
repasimotorwerks.com

Invoice #3664

Created: 05/13/2026
Invoiced: 08/31/2026
Payment Term: On Receipt
Payment Due: 08/31/2026

[redacted]

2007 Porsche 911 Turbo
VIN: WP0AD29987S785047
Mileage In: 49,670 mi
Mileage Out: 49,708 mi

Client States Brake Pedal Sticks Down When Driving

Description	Price	QTY	HRS	Disc	Subtotal
Labor: Check & Report *Perform road test, found car stops evenly, but pedal feel is stiff compared to similar 997 Turbo and pedal has a delayed return. Access brake booster and observed hissing noise indicating leak. Check vacuum while running, 25in-hg from vacuum pump, OK. Smoke test booster, found smoke leaking out of seal between brake servo and booster. Remove servo and found pushrod inside booster is off center. Remove booster and found piston inside falls out and parts rattling around inside booster. Intermediate pushrod cannot be locked into place due to plastic tabs not holding securing ring. Used booster on order.*			2	15%	$433.50
Labor: Replace Brake Booster *Remove ABS unit, brake tubes, and ABS unit. Replace brake booster with good used part. Swap over intermediate pushrod and secure in place. Swap over dampening seal and boot. Assemble brake servo to booster on bench and fill with fluid to bench bleed. Fit assembly to car, set pushrod length, and re-torque pedal bushing shaft nut. Refit ABS and brake tubes. Perform preliminary brake bleed and flush, then ABS bleed and final brake bleed. Secure boot with new clamps, replace 1 missing bleed screw cap in rear left, and torque wheel lug bolts. Check for vacuum leaks at booster, OK. Perform road test and verify brake pedal is normal compared to similar 997 Turbos.*			4.5	15%	$975.38
Part: Brake Booster (USED)	$625.00	1			$625.00
				Discount (10.89%): $248.63	**Total: $2,033.87**

Brake Fluid Flush

Due Every Two Years Per Porsche Maintenance Schedule

Repasi Motorwerks LLC
1701 Stratford Avenue
Stratford, CT 06615
(203) 257-0987
info@repasimotorwerks.com
repasimotorwerks.com

Invoice #3664

Created: 05/13/2026
Invoiced: 08/31/2026
Payment Term: On Receipt
Payment Due: 08/31/2026

Brake Fluid Flush

Description	Price	QTY	HRS	Disc	Subtotal
Labor: Perform Brake Fluid Flush *Brake fluid flush due every two years per Porsche Maintenance Schedule. Brake fluid flush due every year if vehicle is to be driven on track. Remove wheels and pressurize brake fluid system. Bleed all brake calipers inboard and outboard bleed valves. Set brake fluid level to proper level. Mount wheels and torque wheel bots to spec.*			2	15%	$272.00
Labor: Perform ABS System Flush *Use PIWIS to flush ABS system and activate valves.*			2	15%	$272.00
Part: Porsche DOT 4 Brake Fluid	$42.50	3			$127.50
Part: Cap for Brake Caliper Bleed Screw	$5.07	1			$5.07
	Discount (12.43%): $96.00	EPA: $2.50	Shop Supplies: $5.00		**Total: $684.07**

During Inspection Technician Noted Rear Spoiler Does Not Operate And A Warning Comes On The Cluster While Driving

Install Electric Conversion Kit - 997 Turbo Rennkit Eram Rear Spoiler

Description	Price	QTY	HRS	Disc	Subtotal
Labor: Install Rennkit Eram Rear Spoiler Drive			5	15%	$998.75
Labor: Recode Spoiler Drive *Rear spoiler was previously worked on. Previous shop attempted to code out operation of rear spoiler. After installed code rear spoiler back to operate*			1	15%	$208.25
Part: Rennkit E-ram Spoiler Drive	$1,649.00	1			$1,649.00
Fee: Shipping					$75.00
	Discount (6.94%): $213.00		Shop Supplies: $17.50		**Total: $2,948.50**

During Inspection Technician Noted Parking Brake Is Out Of Adjustment

Adjust Parking Brake

Description	HRS	Disc	Subtotal
Labor: Adjust Parking Brake	0.5	15%	$99.88
		Discount (15%): $17.63	**Total: $99.87**

During Inspection Technician Noted Clutch Catches High And Chatters

Replace Clutch Kit And Dual Mass Flywheel

Repasi Motorwerks LLC
1701 Stratford Avenue
Stratford, CT 06615
(203) 257-0987
info@repasimotorwerks.com
repasimotorwerks.com

Invoice #3664

Created: 05/13/2026
Invoiced: 08/31/2026
Payment Term: On Receipt
Payment Due: 08/31/2026

During Inspection Technician Noted Clutch Catches High And Chatters

Description	Price	QTY	HRS	Disc	Subtotal
Labor: Replace Clutch Kit And Dual Mass Flywheel			12	15%	$2,397.00
Part: Dual Mass Flywheel	$1,516.05	1		10%	$1,364.45
Part: Flywheel Bolt	$8.86	9		10%	$71.77
Part: Clutch Disc	$620.26	1		10%	$558.23
Part: Pressure Plate	$789.59	1		10%	$710.63
Part: Pressure Plate Bolt	$3.88	9		10%	$31.43
Part: Release Bearing *Part #: 950 116 080 09*	$328.46	1		10%	$295.61
Part: Fork Bearing Set *Part #: 10 1518 086*	$150.16	1		10%	$135.14
Part: Hydraulic Clutch Fluid *Part #: 000 043 305 74*	$26.25	1		10%	$23.63
	Discount (12.22%): $777.56		Shop Supplies: $22.50		**Total: $5,610.37**

Client Requests To Read Out DME Over Revs

Description	Subtotal
	Total: $0.00

Hand Wash Vehicle For Delivery

Description	Price	Subtotal
Subcontract: Hand Wash Vehicle For Delivery	$100.00	$100.00
	Discount (100%): $100.00	**Total: $0.00**

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Please contact us if you have any questions or concerns. Any vehicle not picked up within 5 business days of completion may be subject to daily storage fees. Any parts removed from your vehicle not picked up within 30 days of completion will be forfeited and no longer responsibility of Repasi Motorwerks LLC.

Signature _____

Labor	$6,655.00
Parts	$5,952.00
Subcontracts	$100.00
Subtotal	$12,707.00
Discount	$1,452.82
Shop Supplies	$45.00
EPA	$2.50
Fees	$75.00
Tax	$0.00
Grand Total	**$11,376.68**
Paid to Date	($0.00)
REMAINING BALANCE	**$11,376.68**