

TODD SNYDER
NEW YORK

450764

INVOICE

FLETCHER JONES

M · O · T · O · R · C · A · R · S

NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200
Service Fax (949) 718-3380

NEWPORT BEACH, CALIFORNIA 92660

MON - FRI: 7:00 A.M. - 7:00 P.M.

SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday

BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672

EPA # CAL000266553

PAGE 1

SERVICE ADVISOR: 2578 JERRY CORONA

BUS:	COLOR	YEAR	MA	VIN	LICENSE	MILEAGE IN/ OUT	TAG
		23	MERCEDES G63	W1NYC7HJ0PX466361		40867/40877	T5347
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE	PAYMENT	INV. DATE
03MAR23 DD			17:00 25SEP26			CASH	25SEP26
R.O. OPENED	READY	OPTIONS: DLR:75563					

15:51 10SEP26 16:47 25SEP26

LINE OPCODE TECH TYPE HOURS

A GUEST STATES CHECK ENGINE LIGHT IS ON. CK AND ADVISE.

CAUSE:

540650 ON-BOARD POWER SUPPLY VOLTAGE MAINTAIN
(WHEN CHECKING/ TESTING AND TROUBLESHOOTING)

26761 W67

541011 PERFORM QUICK TEST

26761 W67

070640 CHECK ENGINE (AFTER QUICK TEST)

26761 W67

185036 OIL PRESSURE CONTROL VALVE ON OIL PUMP
REMOVE/INSTALL, INSPECT AND, IF NECESSARY,
REPLACE (OIL PAN REMOVED)

26761 W67

017504 REMOVE/INSTALL/SEAL OIL PAN (TRANSMISSION
REMOVED)

26761 W67

272030 REMOVE/INSTALL AUTOMATIC TRANSMISSION ON
VEH. WITH TRANSMISSION 725.0

26761 W67

271260 CHECK/CORRECT OIL LEVEL IN AUTOMATIC
TRANSMISSION VIA ULTRASOUND (AFTER LEAK
TEST) ON VEH. WITH TRANSMISSION

26761 W67

274811 EXTRA WORK FOR: REMOVE/INSTALLTORQUE
CONVERTER ON VEH. WITH TRANSMISSION 725.0

26761 W67

547989 DISCONNECT/CONNECT GROUND LINEOF BATTERY
FOR 12 V ON-BOARD ELECTRICAL SYSTEM (DURING
REPAIR OPERATIONS)

26761 W67

401580 REMOVE/INSTALL COMPLETE WHEEL

26761 W67

401470 EXTRA WORK FOR: REMOVE/INSTALLWHEEL AND
TIRE ASSEMBLY WHEN MOUNTING WITH A WHEEL

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE.	DESCRIPTION	TOTALS
	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED	CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	LABOR AMOUNT	
DATE	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT. PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.			PARTS AMOUNT	
	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.			GAS, OIL, LUBE	
CALLER BY	CUSTOMER ACCEPTANCE		PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.	SUBLET AMOUNT	
	X I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			MISC. CHARGES	
OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MUTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.				TOTAL CHARGES	
				EXT PAYMENT	
				SALES TAX	
				PLEASE PAY THIS AMOUNT →	

CUSTOMER COPY

TODD SNYDER

NEW YORK

450764

INVOICE

FLETCHER JONES

M·O·T·O·R·C·A·R·S

NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200

Service Fax (949) 718-3380

NEWPORT BEACH, CALIFORNIA 92660

MON - FRI: 7:00 A.M. - 7:00 P.M.

SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday
BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672
EPA # CAL000266553

PAGE 2

SERVICE ADVISOR: 2578 JERRY CORONA

COLOR	YEAR	VIN		LICENSE	MILEAGE IN/ OUT	TAG
	23	W1NYC7HJ0PX466361			40867/40877	T5347
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE	PAYMENT
03MAR23 DD			17:00 25SEP26			CASH
R.O. OPENED	READY	OPTIONS: DLR:75563				25SEP26

15:51 10SEP26	16:47 25SEP26
---------------	---------------

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

LIFT DOLLY		
26761 W67		
611086 LOWER ENGINE COMPARTMENT PANELING FRONT		(N/C)
AND CENTER PARTS REMOVE/INSTALL		
26761 W67		
015023 REMOVE/INSTALL ENGINE COVER		(N/C)
26761 W67		
1 278-180-04-15 HYD. DIRECT. CTRL. VALVE		(N/C)
#18L 428		(N/C)
1 177-150-38-20 ELECTRICAL WIRING HARNESS		
1 029-997-22-45 O-RING		(N/C)
20 910143-006002 HEXALOBULAR SCREW		(N/C)
1 003-989-98-20-10 SEALANT		(N/C)
1 007603-014106 SEALING RING		(N/C)
1 000-989-71-10-09-0109 MB 325.6 G40		(N/C)
ANTI-FREEZE 1 GALLON BASF		
#18L		(N/C)
1 002-989-06-03-12 TRANSMISSION FLUID		(N/C)
2 023-997-04-45-64 O-RING		(N/C)
2 012-997-56-48 SEALING RING		(N/C)
2 023-997-82-48-64 SEALING RING		(N/C)
1 278-180-00-09-90 STARPART TS OIL FILTER		(N/C)
ELEMENT		
2 910143-008006 HEXALOBULAR SCREW		(N/C)
2 203-490-06-41 PIPE CLAMP, EXHAUST SYS.		(N/C)
3 000000-008299-64 NUT-AND-WASHER ASSEMBLY		(N/C)
2 000000-008268-65 NUT		(N/C)
4 910105-014005 HEXAGON HEAD BOLT		(N/C)
6 463-410-16-00 PK, MOUNTING PLATE		(N/C)
6 463-410-15-00 PK, MOUNTING PLATE		(N/C)
2 000-990-75-06 HEXALOBULAR HEAD SCREW		(N/C)
2 005-990-47-50-64 NUT-AND-WASHER ASSEMBLY		(N/C)
2 000000-008267 NUT		(N/C)
4 000-990-39-25 HEXALOBULAR HEAD SCREW		(N/C)

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE.	DESCRIPTION	TOTALS
	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED	CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	LABOR AMOUNT	
DATE	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT. PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.		PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.	PARTS AMOUNT	
	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.			GAS, OIL, LUBE	
CALL BY	CUSTOMER ACCEPTANCE			SUBLET AMOUNT	
	X I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			MISC. CHARGES	
				TOTAL CHARGES	
OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.				EXT PAYMENT	
				SALES TAX	
				PLEASE PAY THIS AMOUNT →	

CUSTOMER COPY

TODD SNYDER
NEW YORK

450764

INVOICE

PAGE 3

FLETCHER JONES
M · O · T · O · R · C · A · R · S
NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200
Service Fax (949) 718-3380

NEWPORT BEACH, CALIFORNIA 92660

MON - FRI: 7:00 A.M. - 7:00 P.M.

SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday

BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672
EPA # CAL000266553

SERVICE ADVISOR: 2578 JERRY CORONA

VIN		LICENSE		MILEAGE IN/ OUT		TAG	
23 MERCEDES G63		W1NYC7HJ0PX466361		40867/40877		T5347	
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE	PAYMENT	INV. DATE
03MAR23 DD			17:00 25SEP26			CASH	25SEP26
R.O. OPENED		READY		OPTIONS:		DLR:75563	
15:51 10SEP26		16:47 25SEP26					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
2	000000-003275		NUT				(N/C)
6	910105-008019		HEXAGON HEAD BOLT				(N/C)
1	025-997-39-45		O-RING				(N/C)
1	177-181-06-00		ELASTOMERIC MOLDED SEAL				(N/C)
8	012-990-50-04		CAP SCREW W HEXAL. SOCKET				(N/C)
1	018-990-79-01		HEX. HEAD SCREW W FLANGE				(N/C)
1	177-010-24-00		ELASTOMERIC MOLDED SEAL				(N/C)
9	000000-001144		HEXALOBULAR SCREW				(N/C)
1	177-010-37-08		CRANKCASE COVER				(N/C)
#18L							
1	177-010-04-00		CRANKCASE COVER				(N/C)
#18L							
13	000000-001144		HEXALOBULAR SCREW				(N/C)
#18L							

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

40872 MILES IN: 40867 #R WARRANTY; (337-334415 1.5 ZM AUTHO FOR
DIAG & ELECTRICAL TESTING (.1 BATTERY MAINTAINER, .2 QUICK TEST, 1.2
ELECTRICAL TESTING) (01-5023, 54-7989, 61-1086, 27-2030, 27-4811,
40-1580, 40-1470, 01-7504, 18-5036, 27-1260, 27-1048) CONCERN: CHECK
ENGINE LIGHT IS ON. CAUSE: OPEN CIRCUIT IN OIL CONTROL VALVE.
CORRECTION: APPLIED BATTERY MAINTAINER. PERFORMED QUICK TEST & FOUND
FAULT CODE IN THE ENGINE CONTROL UNIT (P06DA00- The actuation of the
valve of the oil pump in the combustion engine has an electrical fault
or open circuit). PERFORMED GUIDED TESTING, FOUND OIL CONTROL VALVE
DOES NOT SWITCH ON WHEN BEING ACTUATED. REMOVED ENGINE COVER. APPLIED
SOCKET BOX TO ME CONTROL UNIT. PERFORMED POWER SUPPLY CHECK FOR OIL
CONTROL VALVE, FOUND 13V ARE PRESENT & MEASURED VALUE IS OKAY. CHECKED
RESISTANCE OF OIL CONTROL VALVE, FOUND RESISTANCE MEASURED AS OPEN
CIRCUIT. PER GUIDED TESTING WILL NEED TO REPLACE OIL CONTROL VALVE.
DISCONNECTED GROUND LINE OF 12V BATTERY. REMOVED WHEELS, USED WHEEL
LIFT DOLLY. REMOVED FRONT & CENTER LOWER ENGINE COMPARTMENT PANELING.
DRAINED ENGINE OIL. DRAINED COOLANT. REMOVED AUTOMATIC TRANSMISSION,
EXTRA WORK FOR REMOVING TORQUE CONVERTER ON 725.0 TRANSMISSION. REMOVED
OIL PAN. REPLACED OIL CONTROL VALVE. REASSEMBLED ALL COMPONENTS IN

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	DESCRIPTION	TOTALS
	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED		LABOR AMOUNT	
DATE	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT. PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.		PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.	PARTS AMOUNT	
CALL BY	CUSTOMER ACCEPTANCE			GAS, OIL, LUBE	
	X I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			SUBLET AMOUNT	
OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MUTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.				MISC. CHARGES	
				TOTAL CHARGES	
				EXT PAYMENT	
				SALES TAX	
				PLEASE PAY THIS AMOUNT	➔

CUSTOMER COPY

TODD SNYDER
NEW YORK

450764

INVOICE

PAGE 4

FLETCHER JONES
MOTORCARS
NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200
Service Fax (949) 718-3380
NEWPORT BEACH, CALIFORNIA 92660
MON - FRI: 7:00 A.M. - 7:00 P.M.
SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday
BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672
EPA # CAL000266553

SERVICE ADVISOR: 2578 JERRY CORONA

COLOR	YEAR	VIN	LICENSE	MILEAGE IN/ OUT	TAG
	23	MERCEDES G63			
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE
03MAR23 DD			17:00 25SEP26		
R.O. OPENED	READY	OPTIONS:	DLR:75563	PAYMENT	INV. DATE
				CASH	25SEP26

15:51 10SEP26 16:47 25SEP26

LINE OPCODE TECH TYPE HOURS

	LIST	NET	TOTAL
REVERSE ORDER. FILLED ENGINE WITH 9.5 LITERS OF 299.5 5W-40. FILLED & PERFORMED BLEEDING FOR COOLING SYSTEMS. PERFORMED ADAPTATIONS AFTER REPAIRS. CHECKED & CORRECTED OIL LEVEL IN AUTOMATIC TRANSMISSION. CLEARED ALL FAULT CODES. PERFORMED VEHICLE ROAD TEST, FOUND CHECK ENGINE LIGHT DID NOT RETURN. MILES OUT: 40872			

B CHECK AND CORRECT TIRE PRESSURES AS NEEDED
CAUSE: CHECKED TIRE PRESSURE AND CORRECTED TO L/F R/F L/R R/R
TIRE CHECK AND CORRECT TIRE PRESSURES AS NEEDED

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00
40867	CHECK AND CORRECT TIRE PRESSURES: L/F 38 R/F 38 L/R 35 R/R 35						0.00

C FLETCHER JONES MOTORCARS 30-DAY RETURN MULTI-POINT INSPECTION - CHECK AND CORRECT TIRE PRESSURES AS NEEDED
CAUSE: CHECKED TIRE PRESSURE AND CORRECTED TO L/F R/F L/R R/R
30MPI FLETCHER JONES MOTORCARS 30-DAY RETURN MULTI-POINT INSPECTION - CHECK AND CORRECT TIRE PRESSURES AS NEEDED

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE C:	0.00
40867	PERFORMED 30 DAY RETURN MPI						0.00

D COURTESY CAR WASH

94-100 COURTESY CAR WASH

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE D:	0.00
							0.00

E MY SERVICE ADVISOR HAS ASKED ME TO REMOVE ALL MONEY & VALUABLES FROM MY VEHICLE. MY SIGNATURE ON THIS REPAIR ORDER ACKNOWLEDGES THAT FLETCHER JONES MOTORCARS IS NOT RESPONSIBLE FOR ANY LOST OR STOLEN PERSONAL ITEMS.

333 MY SERVICE ADVISOR HAS ASKED ME TO REMOVE ALL MONEY & VALUABLES FROM MY VEHICLE. MY

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	DESCRIPTION	TOTALS
	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED		LABOR AMOUNT	
DATE	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT. PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.			PARTS AMOUNT	
CALL BY	CUSTOMER ACCEPTANCE			GAS, OIL, LUBE	
	X I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			SUBLET AMOUNT	
	PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.			MISC. CHARGES	
	OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MULTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.			TOTAL CHARGES	
				EXT PAYMENT	
				SALES TAX	
				PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

TODD SNYDER
NEW YORK

450764

INVOICE

FLETCHER JONES
MOTORCARS
NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200
Service Fax (949) 718-3380

NEWPORT BEACH, CALIFORNIA 92660

MON - FRI: 7:00 A.M. - 7:00 P.M.

SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday
BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672
EPA # CAL000266553

PAGE 5

SERVICE ADVISOR: 2578 JERRY CORONA

BUS:	COLOR	YEAR	VIN	LICENSE	MILEAGE IN/ OUT	TAG
		23	W1NYC7HJ0PX466361		40867/40877	T5347
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE	PAYMENT
03MAR23 DD			17:00 25SEP26			CASH
R.O. OPENED	READY	OPTIONS:	DLR: 75563			25SEP26

15:51 10SEP26 16:47 25SEP26

LINE OPCODE TECH TYPE HOURS

SIGNATURE ON THIS REPAIR ORDER ACKNOWLEDGES
THAT FLETCHER JONES MOTORCARS IS NOT
RESPONSIBLE FOR ANY LOST OR STOLEN PERSONAL
ITEMS.

PARTS:	2676 CRP	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE E:	0.00
								0.00

F CREDIT CARD TRANSACTIONS WILL BE ASSESSED A 3% PROCESSING FEE -
DEBIT/CASH/ACH(CLERQ) TRANSACTIONS WILL HAVE ZERO PROCESSING
FEES

CCS CREDIT CARD TRANSACTIONS WILL BE ASSESSED A
3% PROCESSING FEE - DEBIT/CASH/ACH(CLERQ)
TRANSACTIONS WILL HAVE ZERO PROCESSING FEES

PARTS:	2676 CRP	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE F:	0.00
								0.00

G** 1816-367129 during inspection, found coolant leaking
CAUSE:

831762 EXTRACT REFRIGERANT, CHECK FORLEAKS,
REFILL (WHEN WORKING ONAIR CONDITIONING)

26761 W67

(N/C)

881102 REMOVE/INSTALL FRONT BUMPER COMPLETE

26761 W67

(N/C)

881089 EXTRA WORK FOR: REMOVE/INSTALLFRONT BUMPER
COMPLETE ON VEH. WITH BODY-STYLING BAR

26761 W67

(N/C)

882164 EXTRA WORK FOR: REMOVE/INSTALLRADIATOR
GRILLE ON VEH. WITH 360-DEGREE CAMERA

26761 W67

(N/C)

204000 REPLACE RADIATOR

26761 W67

(N/C)

304210 PERFORM INITIAL STARTUP OF DISTRONIC
CONTROLLER UNIT

26761 W67

(N/C)

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	DESCRIPTION	TOTALS
DATE	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED	PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.	LABOR AMOUNT	
CALL BY	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT. PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.			PARTS AMOUNT	
	CUSTOMER ACCEPTANCE			GAS, OIL, LUBE	
	X I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			SUBLET AMOUNT	
	OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MUTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.			MISC. CHARGES	
				TOTAL CHARGES	
				EXT PAYMENT	
				SALES TAX	
				PLEASE PAY THIS AMOUNT	

TODD SNYDER
NEW YORK

450764

INVOICE

PAGE 6

SERVICE ADVISOR: 2578 JERRY CORONA

FLETCHER JONES

M · O · T · O · R · C · A · R · S

NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200
Service Fax (949) 718-3380

NEWPORT BEACH, CALIFORNIA 92660

MON - FRI: 7:00 A.M. - 7:00 P.M.

SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday
BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672

EPA # CAL000266553

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
	23	MERCEDES G63	W1NYC7HJ0PX466361		40867/40877	T5347	
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE	PAYMENT	INV. DATE
03MAR23 DD			17:00 25SEP26			CASH	25SEP26
R.O. OPENED	READY	OPTIONS: DLR:75563					
15:51 10SEP26	16:47 25SEP26						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	167-500-63-01	COOLANT RADIATOR					(N/C)
	#L18	2260					
1	000-989-71-10-09-0109	MB 325.6 G40					(N/C)
	ANTI-FREEZE	1 GALLON BASF					(N/C)
1	023-997-62-45-64	PROFILE SEALING RING					(N/C)
	L-18						
1	023-997-63-45	PROFILE SEALING RING					(N/C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE G:	0.00

40872 MILES IN: 40867 #R WARRANTY; (83-1762, 88-1102, 88-1089, 88-2164, 20-4000, 30-4210) DURING INSPECTION FOUND RADIATOR IS LEAKING FROM THE BOTTOM LEFT CORNER. EXTRACTED REFRIGERANT. REMOVED THE COMPLETE FRONT BUMPER, EXTRA WORK FOR R&R BUMPER ON VEHICLE WITH BODY STYLING BAR. EXTRA WORK FOR REMOVING RADIATOR GRILLE ON VEHICLE WITH 360 CAMERA. REPLACED RADIATOR. CHARGED REFRIGERANT WITH THE SAME AMOUNT THAT WAS EXTRACTED. PERFORMED INITIAL STARTUP OF DISTRONIC CONTROL UNIT. PERFORMED VEHICLE ROAD TEST. FOUND NO COOLANT LEAKS ARE PRESENT AFTER ROAD TEST. MILES OUT: 40872

H** 337-334416 FOR ALIGNMENT AFTER REPAIRS

CAUSE: .

406500 PERFORM WHEEL ALIGNMENT CHECK

23272 W67

(N/C)

406510 EXTRA WORK FOR: WHEEL ALIGNMENT CHECK:

PERFORM TOE ADJUSTMENT ON FRONT AXLE

23272 W67

(N/C)

304210 PERFORM INITIAL STARTUP OF DISTRONIC

CONTROLLER UNIT

23272 W67

(N/C)

304220 PERFORM DISTRONIC CALIBRATION (AFTER

INITIAL STARTUP)

23272 W67

(N/C)

PARTS:

0.00

LABOR:

0.00

OTHER:

0.00

TOTAL LINE H:

0.00

40877

WARRANTY DISTRONIC ALIGNMENT (40-6500 0.70 H, 40-6510 ZM 0.40 H,

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE. CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	DESCRIPTION	TOTALS
	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED		LABOR AMOUNT	
DATE	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT. PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK. I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.		PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.	PARTS AMOUNT	
	CUSTOMER ACCEPTANCE			GAS, OIL, LUBE	
CALLED BY	X			SUBLET AMOUNT	
	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			MISC. CHARGES	
OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MUTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.				TOTAL CHARGES	
				EXT PAYMENT	
				SALES TAX	
				PLEASE PAY THIS AMOUNT	

TODD SNYDER
NEW YORK

450764

INVOICE

PAGE 7

FLETCHER JONES

M · O · T · O · R · C · A · R · S

NEWPORT BEACH

3300 Jamboree Rd. Phone (949) 718-3200
Service Fax (949) 718-3380

NEWPORT BEACH, CALIFORNIA 92660

MON - FRI: 7:00 A.M. - 7:00 P.M.

SAT: 8:00 A.M. - 1:00 P.M. Sprinter Closed Saturday

BAR # ARD 164440 EPA # CAR 000040113 EPA # CAL 000466672

EPA # CAL000266553

SERVICE ADVISOR: 2578 JERRY CORONA

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
	23	MERCEDES G63	W1NYC7HJ0PX466361		40867/40877	T5347	
IN SERVICE DATE	PROD. DATE	WARR. EXP.	TARGET DATE	PO NO.	RATE	PAYMENT	INV. DATE
03MAR23 DD			17:00 25SEP26			CASH	25SEP26
R.O. OPENED	READY	OPTIONS: DLR:75563					
15:51 10SEP26	16:47 25SEP26						
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

30-4210 0.10 H, 30-4220 ZM 1.00 H)

AUTHO CODE FOR DTR INITIAL START-UP(0.1) AND CALIBRATION DRIVE (ZM

1.0) : 1367-368420

PERFORMED COMPUTERIZED DISTRONIC ALIGNMENT. PERFORMED INITIAL START UP OF DISTRONIC CONTROL UNIT. FOLLOWING WITH DISTRONIC CALIBRATION VIA TEST DRIVE. MILES IN: 40872. MILES OUT: 40877. CHECKED VEHICLE AXLE INCLINATION WITH ROMES (0.7). CHECKED AND ADJUSTED TIRE PRESSURES TO VEHICLE SPECIFICATION, 38 PSI FRONT AND 35 PSI REAR. DISENGAGED EASY ENTRY. INSPECTED VEHICLE UNDERCARRIGE AND SUSPENSION COMPONENTS FOR DAMAGE. CENTERED STEERING WHEEL AND SET FRONT TOE(ZM 0.4).

FRONT CAMBER L -1.09 R -1.07

FRONT CASTER L 3.04 R 2.93

FRONT TOE L 0.21 R 0.20

REAR CAMBER L -0.22 R -0.32

REAR TOE L 0.02 R 0.05

REAR TOTAL TOE 0.07

RE-ENGAGED EASY ENTRY. PERFORMED VEHICLE TEST DRIVE AFTER

ADJUSTMENTS, FOUND VEHICLE TRACKING NORMALLY ON ALIGNMENT TEST ROADS, NORMAL ROAD CROWN AT THIS TIME. NORMAL STEERING INPUT NEEDED ON CROWNED ROADS.

ORIGINAL ESTIMATE \$

AUTHORIZED ESTIMATE \$

I ACKNOWLEDGE NOTICE OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUST OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.

X

TIME	ORIGINAL ESTIMATE \$	AUTHORIZED ADDITIONS \$	ALL PARTS ARE NEW UNLESS SPECIFIED OTHERWISE.	DESCRIPTION	TOTALS
	☐ IN PERSON ☐ BY PHONE	PERSON CONTACTED	CODES: (PRECEDING PART NUMBER) A-VENDOR OTHER THEN MBUSA 70-CORE CHARGE/CREDIT 88-REBUILT PART, CORE REQUESTED 80-REBUILT PART, CORE REQUESTED.	LABOR AMOUNT	0.00
DATE	SUBJECT TO CONDITIONS ON REVERSE SIDE OF THIS CONTRACT, PLEASE READ REVERSE SIDE. NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.			PARTS AMOUNT	0.00
	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE AND ADDITIONAL CUSTOMER OR WARRANTY WORK PERFORMED, AND/OR RECEIPT OF VEHICLE.			GAS, OIL, LUBE	0.00
CALL BY	CUSTOMER ACCEPTANCE		PART NUMBERS ENDING WITH AN A ARE NOT MBUSA SUPPLIED PARTS. THESE PARTS ARE NOT WARRANTED BY MBUSA FLETCHER JONES MOTORCARS WILL WARRANT THESE PARTS FOR 24 MONTHS. UNLIMITED MILEAGE NO LABOR.	SUBLET AMOUNT	0.00
	X			MISC. CHARGES	0.00
	I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATE PRICE (WARRANTY IF APPLICABLE)			TOTAL CHARGES	0.00
OUR CHARGES ARE NOT BASED ON ACTUAL TIME BUT ARE ESTABLISHED BY MUTIPLYING OUR RETAIL LABOR RATE BY INDUSTRY FLAT RATE ALLOWANCES OR OUR OWN EXPERIENCE OF THE AVERAGE TIME.				EXT PAYMENT	0.00
				SALES TAX	0.00
				PLEASE PAY THIS AMOUNT	0.00